

Photo Log - ENPRO, South Portland, ME - May 24 - 26, 2010

- Photo #1 - Cell A "Corrosive", Universal Waste, Electronic Waste, Non - Haz Waste
- Photo #2 - Cell A, Universal Waste, Electronic Waste, Non - Hazardous Waste
- Photo #3 - Cell B, "Corrosive", Hazardous Waste, 10 day storage items
- Photo #4 - Cell B, Hazardous Waste, 10 day storage items
- Photo #5 - Cell D, "Waste Gasoline"
- Photo #6 - Cell D, Waste Gasoline
- Photo #7 - Cell C "Ignitable", Waste Gasoline, Torch Supplies, 10 day storage items
- Photo #8 - Cell C, Hazardous Waste Labels
- Photo #9 - Cell C, Hazardous Waste Labels
- Photo #10 - Cell C, Waste Gasoline Drums
- Photo #11 - Cell C, 10 day storage items
- Photo #12 - Cell C, Waste Gasoline, Cutting Torch Supplies, 10 day storage items
- Photo #13 - Waste Water Treatment System
- Photo #14 - Waste Water Treatment System
- Photo #15 - Waste Water Treatment System
- Photo #16 - Waste Water Treatment System
- Photo #17 - Waste Water Treatment System
- Photo #18 - Waste Water Treatment System
- Photo #19 - Waste Water Treatment System
- Photo #20 - Waste Water Treatment System
- Photo #21 - Waste Water Treatment System
- Photo #22 - Waste Water Treatment System
- Photo #23 - Waste Water Treatment System
- Photo #24 - Trailer, Hazardous Wastes
- Photo #25 - Trailer, Flammable Solid Wastes
- Photo #26 - Container Storage Room
- Photo #27 - Waste Oil Tanks #1 and #2
- Photo #28 - Roll - Off "RO - 02"
- Photo #29 - Waste Oil Tanks (street view), Tank#3 (insulated)
- Photo #30 - Waste Gasoline Tank
- Photo #31 - Waste Oil Tanks #1 (air emission issue)
- Photo #32 - Waste Oil Tanks #3 (air emission issue)
- Photo #33 - Waste Gasoline Tank (air emission issue)
- Photo #34 - Waste Gasoline Tank (air emission issue)
- Photo #35 - Waste Gasoline Tank Hoses
- Photo #36 - Waste Gasoline Tank "Red" Hose (air emission issue)
- Photo #37 - Waste Gasoline Tank (air emission issue)
- Photo #38 - Waste Gasoline Tank (air emission issue)
- Photo #39 - Roll - Off (weld marked 208634)
- Photo #40 - Roll - Off (weld marked 208634)
- Photo #41 - Roll - Off "RO - 77"
- Photo #42 - Roll - Off "RO - 77"
- Photo #43 - Roll - Off (weld marked 309703)
- Photo #44 - Roll - Off (weld marked 309703)
- Photo #45 - Roll - Off "RO - 03"
- Photo #46 - Roll - Off "RO - 03"
- Photo #47 - Roll - Off (weld marked 201738)
- Photo #48 - Roll - Off (weld marked 201738)

Photo Log - ENPRO, South Portland, ME - May 24 - 26, 2010 (cont'd)

Photo #49 - Roll - Off (crushed empty drums); Storage Container  
Photo #50 - Trailer, Hazardous Wastes  
Photo #51 - Roll - Off "RO - 02"  
Photo #52 - Drum Sampling Preparation  
Photo #53 - Drum Sampling Preparation  
Photo #54 - Tank Sampling Preparation - Sampling Tube Assembly  
Photo #55 - Tank Sampling - Sampling Tube Draining

Photo numbered across then down on thumbnail prints

See Q:\Share\RCRA\ENPRO Photos

D. MacLeod 5/27/10

Attachment